

ENGINE MAINTENANCE RECORDS

Log No. _____

Aircraft Registration No. N777PC

Engine Manufacturer CONTINENTAL

Model TS10-550-E

Serial No. 803164

Date installed on aircraft 7/10/2002

Time Between Overhauls (TBO) _____ Hours

If used on multi-engine aircraft:

- | | |
|--------------------------------|-------------------------------|
| <input type="checkbox"/> Right | <input type="checkbox"/> Left |
| <input type="checkbox"/> Front | <input type="checkbox"/> Rear |



AEROTECH PUBLICATIONS INC.

www.adlog.com
PO BOX 1359 / SOUTHOLD, NY 11971-0965
(631) 765-9375
1-800-235-6444
FAX: (631) 765-9359

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page
7-10-02	0	0	0	Continental TS10 550 E SN 803164 installed on N777PC in accordance with Lancair and Continental manual. Engine ops normal Maintenance Manual Repairman Experimental Aircraft Builder Certificate number 2715814
4-28-09			.4 HRS	Performed Annual/Condition Inspection. Compression #1 75/80 #2 78/80 #3 74/80 #4 78/80 #5 74/80 #6 79/80. REPLACED OIL FILTER. Inspected Oil Pumper Inspected and cleaned TXR GASOLATOR. Checked ALL AD'S THROUGH THIS DATE I CERTIFY THIS ENGINE HAS BEEN INSPECTED I.A.W. FAR PART 43 APPENDIX D AND FOUND TO BE IN A CONDITION FOR SAFE OPERATION. Tim Lyle AP2751361
5/3/09	0.7		0.7	LEFT TURBOCHARGER REMOVED (S/N EAL0205) SENT TO APPROVED TURBO COMPONENTS, VISALIA CA, FOR REPAIR, OIL LEAK. <i>Atlang</i> A&P 1576532.
5/10/09	0.7		0.7	TURBOCHARGER S/N EAL0205 OVERHAULLED BY ATC, VISALIA, CA INSTALLED ON LEFT SIDE AND OPERATIONALLY CHECKED PER KELLY ADAMS/SPACED SB-NO. 23. FRA FORM 8130-3 IN AIRCRAFT RECORDS. <i>Atlang</i> A&P 1576532
				SUB-TOTALS this page
				TOTALS—Carry forward to next page

